SITE INSPECTION REVIEW FORM

SITE NAME: NORDA INC.	
ALIASES:	
SITE 1.D.#:NJD001307115	
ITEM	COMPLETE ? YES NO*
SITE LOCATION (INCLUDING MAP)	
SITE BACKGROUND	
ENVIRONMENTAL SETTING (GEOLOGY, HYDROLOGY, METEOROLOGY, ECOLOGY + LAND USE)	
WASTE DESCRIPTION (PRESENCE + CONDITION OF WASTE + WASTE MANAGEMENT UNITS)	
LABORATORY RESULTS (CORRELATED TO SAMPLE LOCATION MAP)	
HRS FRE - SCORE (PRELIMINARY + PROJECTED)	
POTENTIAL FOR DIRECT CONTACT	
CONCLUSIONS + RECOMMENDATIONS	<u></u>
REFERENCES	
HRS PRE-SCORE: PRELIMINARY SCORE = 46-90	
PROJECTED SCORE = 54-75	

COMMENTS:

This site is a high privily and L.S.I. condidate. Ground vater contamination is pertrosince follows the entire Township of East Hanover; NJDEP has delineated the area a Well Restriction Area. Insundwater targets are at a maximum; 100,000 people within a 4-mile radius of the site are severally ground water. Sampling data demonstrate soil contamination by volatile organic compounds which appear in the ground water as well although any number of other input sources may account for similar organic compounds having contaminated the aguifar. The projected air migration pathway should not have been scored; I inflotes the overall score (Sm) somewhat. There is a small mathematical error in this score.

Further sampling is not required it this time. NJDEP-BEECRA should oversee remedial efforts.

REVIEWED BY: LARRY TANNENBAUM

DATE: FEB- 20,1990

*IF ANY ITEM IS LACKING INFORMATION PLEASE DESCRIBE IN COMMENTS